

Field Installable FlexConnector

Installation Manual

Field Installable FlexConnector - FLATdrop

Step 1: Prep cable to YOURx length (12 inches) cutting strength members flush with black, outer cable sheath.



Figure 1

Step 2: For water tight seal on standard FLATdrop, feed the following length of heat shrink onto cable for later use:

(1) 3/4" x 3" long (004719)



Figure 2

- **Step 3**: For water tight seal on SFF, feed the following lengths of heat shrink onto cable for later use:
- (1) 3/4" x 3" long (004719)
- (1) 5/16" x 3" long (004458)



Figure 3

Step 4: Pass breakout 3mm/900 micron cable through FlexConnector.




Figure 4

Step 5: Stop short of cable sheath.




Figure 5

Step 6: Align nose of clips to end of black cable and sandwich together.



Step 7: Attach clips to top and bottom of cable, teeth in, even at cable sheath opening. A groove on the clip allows for proper alignment.



Field Installable FlexConnector

Installation Manual



Step 8: Use pliers (as shown) to pinch teeth to hold jacket.

DO NOT use needle nose pliers.

Step 9: Pull FlexConnector (added in Step 4) back over clips to snap into FlexConnector holes, as shown. Push until you hear a snap.

Step 10: **For SFF cable only**, slide the smallest heatshrink, placing one end just inside the back end of the Flex-Connector. Shrink using a heat gun.



Figure 8



Figure 9



Figure 10

Step 11: Slide the 3" piece (004719) heat shrink tubing, covering the holes on the FlexConnector and heat to shrink.

Step 12 This will create a water tight seal.

Step 13: Terminate fiber to connector per instructions (if applicable).



Figure 11



Figure 12




Figure 13



Clearfield College Product Training

www.seeclearfield.com/training/clearfield-college/ certified-partnership-training.html