


## Furcation Kits

### Description

Available in 1, 2, 6 and 12-fiber kits, the FieldShield Furcation Kit provides all the components to up-jacket and terminate 250 µm FieldShield Pushable Fiber using a 900 µm Splice-On Connectors.



### Pre-Configured Part Numbers

Part Number	Description
FS-900UM-01-03F	FieldShield Furcation Kit for 3 mm jacketing, 1-fiber 900 µm, yellow tubing, 3 feet (914.40 mm)
FS-900UM-02-02F	FieldShield Furcation Kit for 3 mm jacketing, 2-fiber 900 µm, colored tubing, 2 feet (609.60 mm)
FS-900UM-06-02F	FieldShield Furcation Kit for 3 mm jacketing, 6-fiber 900 µm, colored tubing, 2 feet (609.60 mm)
FS-900UM-12-02F	FieldShield Furcation Kit for 3 mm jacketing, 12-fiber 900 µm, colored tubing, 2 feet (609.60 mm)
FS-900UM-24-02F	FieldShield Furcation Kit for 4 mm tube, 12-fiber 900 µm, colored tubing, 36 inches (914.40 mm)
FS-3MM-48-02M	FieldShield Furcation Kit for 5.5 mm jacketing, 48-fiber 3 mm, black tubing, 2 meters (6.56 feet)

## Fiber End Face Cleaning Kits

### Description

The Fiber End Face Cleaning Kit is the ideal solution to clean fiber end faces effectively every time.



### Pre-Configured Part Numbers

Part Number	Description
Cleankit-SC-01	Ferrule and V groove swabs, SFF flat swab, 2.5 mm foam swabs, portable platform, fiber wash MX cleaner pen
Cleankit-LC-01	Ferrule and V groove swabs, SFF flat swab, 1.25 mm ferrule swab portable platform, fiber wash MX cleaner pen
Clean MPO-01	MPO chamois swabs, 25 per tube